

Location: US 280
Section: 15

Pavement Preservation Treatment: Scrub Seal

Section Information:

Placement Date: 8/31/2015
Emulsion/Tack Material: CMS-1P
Target Emulsion Rate (gal/SY): 0.29
Calibrated Emulsion Rate (gal/SY): 0.274
Average Verified Emulsion Rate (gal/SY): 0.278
Aggregate Type: Columbus Granite, 89s
Target Chip Rate (lb/SY): 16
Verified Chip Rates (lb/SY): Found Below
Milled Depth: N/A

Left-Wheel Path:

Placement Date: 8/31/2015
Emulsion/Tack Material: CMS-1P
Target Emulsion Rate (gal/SY): 0.29
Calibrated Emulsion Rate (gal/SY): 0.274
Verified Emulsion Rate (gal/SY): 0.282
Aggregate Type: Columbus Granite, 89s
Target Chip Rate (lb/SY): 16
Verified Chip Rate (lb/SY): 14

Between-Wheel Paths:

Placement Date: 8/31/2015
Emulsion/Tack Material: CMS-1P
Target Emulsion Rate (gal/SY): 0.29
Calibrated Emulsion Rate (gal/SY): 0.274
Verified Emulsion Rate (gal/SY): N/A
Aggregate Type: Columbus Granite, 89s
Target Chip Rate (lb/SY): N/A
Verified Chip Rate (lb/SY): N/A

Right-Wheel Path:

Placement Date: 8/31/2015
Emulsion/Tack Material: CMS-1P
Target Emulsion Rate (gal/SY): 0.29
Calibrated Emulsion Rate (gal/SY): 0.274
Verified Emulsion Rate (gal/SY): 0.273
Aggregate Type: Columbus Granite, 89s
Target Chip Rate (lb/SY): 16
Verified Chip Rate (lb/SY): 15

Microsurface Information:

Placement Date: 8/31/2015
Target Microsurface Rate (lb/SY): N/A
Verified Microsurface Rate (lb/SY): N/A

General Notes: